

IEQ SCHOOL DATA BASE

School Name: Waverly Elementary School

Principal: Kathy Jacobs

DATE: January 19, 2017

IEQ Team Leader: Rachel Edoho-Eket

IEQ System Leader: Olivia Claus

LOOK-FORS	ROOM/LOCATION	COMMENTS	ADMIN	FACILITIES	WORK ORDER NUMBER of POTENTIAL IEQ	DATE ASSIGNED	COMPLETION DATE	30 DAY REVISIT
1. No unusual or offensive odors, or temperature discomfort	3602, 3702, 412	hot temperature in room. 412- air leaks		X	HVAC-18273	Jan. 19, 2017		
2. No Air Fresheners	staff lounge, kitchen bathroom	personal bathroom sprays need to be removed	X					
3. No food, dirty lunch boxes, etc. left in room	3716, 3209	food snacks need to be placed in a sealed container	X					
4. Vents are clean and unobstructed	gym storage, 203, 3304(health room) 308, 312, girls/boys first grade bathroom, 401, 402, 406, 407, kitchen area, 501, 502, 3310, 3716, 513 (girls 4th grade bathroom) cafeteria windows, cafeteria storage area, custodial office	exhaust fan vents need to be cleaned/dusted; custodial office: vent cover needs replacement		X	HVAC- 18274	Jan. 19, 2017		
5. Temperature sensors are not blocked								
6. Area appears clean and dust free	girls RECC hallway bathroom, 3712, 3600	general area needs to be cleaned/dusted	X					
7. No signs of animal infestation	308	mouse trap found near door	X					

IEQ SCHOOL DATA BASE

School Name: Waverly Elementary School

Principal: Kathy Jacobs

DATE: January 19, 2017

IEQ Team Leader: Rachel Edoho-Eket

IEQ System Leader: Olivia Claus

<p>8. Ceiling tiles present; no broken, stained, or painted</p>	<p>gym office, 3304(health room) office hallway, AP office, 309, 312, 400, 501, 502, 3320, 3716, 3209, 3210, 311, 3321, 3603, 3604, 3701, 3614, media center, 4th grade pod 114</p>	<p>Stains on ceiling tiles/stained, broken tile and speaker (3304), office hallway: 5 tiles need replacement. AP office: 1 tile needs replacement. 309, 312 & kiln 400,501, 3320, 3716, 3209, 3210, 311, 3603, 3614, media center, 4th grade pod, 3621, 3114 : tiles need replacement/stains. 3604: missing tiles in closet</p>		<p align="center">X</p>	<p>carpentry-18608</p>	<p>Jan. 24, 2017</p>		
<p>9. Walls show no signs of water damage/mildew/ paint irregularities</p>	<p>3320, 3321</p>	<p>water leak in the sun roof</p>		<p align="center">X</p>	<p>carpentry- 18275</p>	<p>Jan. 19, 2017</p>		
<p>10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.</p>	<p>110 (mechanical room)</p>	<p>standing water on the floor</p>		<p align="center">X</p>	<p>HVAC-18609</p>	<p>Jan. 24, 2017</p>		
<p>11. Limited use of non-issued HCPSS furniture and appliances</p>	<p>gym office, teacher's workroom, 404, kitchen area, 3211, 3321, 3714, 3605, 3906, 3701, 3702, 3614, 3611, 3612, 3613, 3635, 3620, 3622, 3621, floor freezer in cafeteria, 112, 114</p>	<p>microwaves, toaster ovens, and personal fridges present. 3211, 3321, 3605, 3701, 3611, 3612, 3635: personal furniture/storage/shelving</p>		<p align="center">X</p>				
<p>12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.</p>	<p>gym office, media rug, 3310, 3321, 3714, 3603, 3605, 3614, 3613, 3624, 3625, 3622, 3621</p>	<p>Media/bean bags, chair cushion, seat pillows / Rugs, cushions, chairs, bean bags & stuffed animals non-compliant. 3310, 3603, 3625 - decorative curtains, 3624: incredible hulk bulletin board</p>		<p align="center">X</p>				
<p>13. No structural or physical gaps around exit doors</p>	<p>3701</p>	<p>hole present in closet wall</p>		<p align="center">X</p>	<p>carpentry-18276</p>	<p>Jan. 19, 2017</p>		
<p>14. No improperly stored materials/chemicals</p>	<p>3211, 3701, 3625</p>	<p>personal cleaners/chemicals present</p>		<p align="center">X</p>				

IEQ SCHOOL DATA BASE

School Name: Waverly Elementary School

Principal: Kathy Jacobs

DATE: January 19, 2017

IEQ Team Leader: Rachel Edoho-Eket

IEQ System Leader: Olivia Claus

15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	boys/girls RECC hall way bathroom, 3209	grate on ceiling should be cleared; tiles need to be closed; 3209 : Escon plate cover on tile needs replacing		X	plumbing- 18295	Jan. 19, 2017		
16. Barrier mats vacuumed well								
17. Fish tanks are clean and located away from vents/thermostats								
18. Waterproof barriers in place for plants and no standing water								
19. Sinks and fountains drain quickly and work properly including absence of leaks	girls/boys 1st grade bathroom,	drains need to be cleaned off		X				
20. No standing water in sinks, fountains, on counter								
21. Carpet dry nearby sinks, fountains	3615	sink shelf missing a door		X	carpentry- 18278	Jan. 19, 2017		
22. Soap and paper towels available	3633, 3634	needs hand soap		X				
23. All electrical outlets secure, no frayed wires on equipment	312, 3321	cord covers need to be ordered for the art room. 3321- cover electrical socket		X	electrical- 18279	Jan. 19, 2017		
24. All electrical cords secured and not extending across walkways								
25. No extension cords used as permanent wiring								

IEQ SCHOOL DATA BASE

School Name: Waverly Elementary School

Principal: Kathy Jacobs

DATE: January 19, 2017

IEQ Team Leader: Rachel Edoho-Eket

IEQ System Leader: Olivia Claus

37. Exterior veneer intact								
38. Outside lights working and intact								
39. Gutters and downspouts clear/working								
40. No stains from roof on outside walls								
41. Bins from garbage and recycling clearly marked								
42. Hard surfaces (sidewalks, etc.) cleared of any turf application								
43. Proper maintenance of planted beds and other vegetation								
44. Landscaping and turf look healthy and disease free								

COMMENTS:

On December 23, 2016 our IEQ team completed a school-wide walkthrough. The main concerns are: (1) There is a large amount of personal shelving/storage present in classrooms (2) many tiles are stained or broken within the building and (3) 18 inch clearance needs to be corrected on top shelves and (4) custodians need improvements when attending to dusty areas

